Appl. No. 10/644,441 Amdt. Dated August 9, 2004

REMARKS

In review of the present application two inconsistencies in the drawings were discovered. Accordingly, the Applicants amend Fig. 2 and Fig. 3.

Specifically, in Fig. 2 the element number 36 for the radial openings was inadvertantly omitted when initially submitting the drawings. Accordingly, element number 36 has been added to Fig. 2. Further, in Fig. 3 the element number L1 was inadvertantly illustrated as equal to L2. Accordingly, L1 has been motified to correctly identify the axial length of the support member 30.

If there are any questions regarding this Preliminary Amendment, please do not hesistate to contact the undersigned at the telephone number listed below.

Respectfully submitted,

GKN Driveline North America, Inc.

Dated: August 9, 2004

Jennifer M. Brupbaugh, Reg. No. 48,465

Mick A. Nylander, Reg. No. 37,200

GKN Driveline North America, Inc.

3300 University Drive

Auburn Hills, MI 48326-2362

(248) 377-1200

Attachments